

**Flood Control Project Maintenance
Levee Inspections**

2016 Channel Summary Report

Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
Duck Creek Diversion Channel

Channel Rating	A
Date of Inspection	7/20/2016
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Diversion Structure / Down

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 1 : CH_2016_NA0017_43_31_20160801_00013.jpg



View of the vegetation in the diversion channel looking downstream during 2016 inspection.

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_1			

Action/Comments

Inspector Comments: No sedimentation was present at this site.

No Photos

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_32			

Action/Comments

Inspector Comments: No erosion or bank caving is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Diversion Structure / Down (cont)

Rating **	N	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_33			

Action/Comments

Inspector Comments: No revetment is present at this location.

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	En	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_34			

Action/Comments

Inspector Comments: No trash or debris observed in the channel.

No Photos

Check Point / View

Farmington Rd/ Hwy 4 / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_11			

Action/Comments

Inspector Comments: The Minimal vegetation in the channel doesn't appear to obstruct the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_43_11_20160801_00014.jpg



View of the vegetation in the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View				
Farmington Rd/ Hwy 4 / Up (cont)				
Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_12			
Action/Comments				
Inspector Comments: No sedimentation was present during inspection.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_13			
Action/Comments				
Inspector Comments: No erosion or bank caving was present during inspection.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap appears to be properly maintained.				

Photo 1 of 2 : CH_2016_NA0017_43_14_20160613_00003.jpg



View of the revetments on the left bank of the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View				
Farmington Rd/ Hwy 4 / Up (cont)				
Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap appears to be properly maintained.				

Photo 2 of 2 : CH_2016_NA0017_43_14_20160801_00016.jpg



View of the revetments on the right bank of the channel looking upstream.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_2			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Farmington Rd/ Hwy 4 / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_16			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel but it doesn't appear to obstruct the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_43_16_20160801_00017.jpg



View of the vegetation looking downstream of the channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_17			

Action/Comments

Inspector Comments: No sediments are present at this location.

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_18			

Action/Comments

Inspector Comments: No bank caving or erosion was found in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Farmington Rd/ Hwy 4 / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_19			
Action/Comments				
Inspector Comments: Existing riprap appears to be properly maintained.				

Photo 1 of 2 : CH_2016_NA0017_43_19_20160801_00018.jpg



View of the revetments on the right bank of the channel looking downstream.

Rating **	A	Issue No.	19 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_19			

Photo 2 of 2 : CH_2016_NA0017_43_19_20160801_00019.jpg



View of the revetments on the left bank of the channel looking downstream.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_20			
Action/Comments				
Inspector Comments: No trash or debris are obstructing the flow of the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Confluence with South Littlejohn Creek / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Action/Comments

Inspector Comments: Vegetation growth in the channel doesn't appeared to impede the flow.

Photo 1 of 4 : CH_2016_NA0017_43_21_20160801_00021.jpg



View of the channel looking upstream during 2016 inspection.

Photo 2 of 4 : CH_2016_NA0017_43_21_20160801_00020.jpg



View of the confluence during 2016 inspection.

Photo 3 of 4 : CH_2016_NA0017_43_21_20160613_00007.jpg



View of the channel looking upstream during 2015 inspection.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View

Confluence with South Littlejohn Creek / Up (cont)

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			

Action/Comments

Inspector Comments: Vegetation growth in the channel doesn't appeared to impede the flow.

Photo 4 of 4 : CH_2016_NA0017_43_21_20160613_00009.jpg



View of the confluence during 2015 inspection.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_22			

Action/Comments

Inspector Comments: No sediment was present at this location.

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_23			

Action/Comments

Inspector Comments: No erosion was present during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	07/20/2016 07/20/2016	Pavel Kazi

Check Point / View				
Confluence with South Littlejohn Creek / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_25			
Action/Comments				
Inspector Comments: No trash or debris are obstructing the flow of the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
North Littlejohn Creek

Channel Rating	A
Date of Inspection	7/20/2016 - 7/26/2016
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Upstream Limit / Up

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_6			
Action/Comments				
Inspector Comments: Minimal vegetation was found, but they do not obstruct the flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_42_6_20160802_00033.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_8			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Upstream Limit / Up (cont)

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_9			

Action/Comments

Inspector Comments: No revetments are found at this location.

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_10			

Action/Comments

Inspector Comments: No trash, debris, or obstruction is present at this location.

No Photos

Check Point / View

Hewit Lane / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_11			

Action/Comments

Inspector Comments: Minimal vegetation exist, but it will not impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_11_20160802_00034.jpg



View of the channel looking upstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Hewit Lane / Up (cont)

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_11			
Action/Comments				
Inspector Comments: Minimal vegetation exist, but it will not impede the flow of the channel.				

Photo 2 of 2 : CH_2016_NA0017_42_11_20160613_00002.jpg



View of the channel looking upstream during 2015 inspection.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_12			
Action/Comments				
Inspector Comments: No sedimentation is present on the channel.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_14			
Action/Comments				
Inspector Comments: Revetments are not present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Hewit Lane / Up (cont)

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_15			

Action/Comments

Inspector Comments: No trash or debris are present in the channel.

No Photos

Rating **	A	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Concrete Surfaces			
DWR ID	DWR_NA0017_42_c_2012_112			

Action/Comments

Inspector Comments: The concrete surface appeared to be in good condition with no negligible spalling, scalling or cracking.

Photo 1 of 1 : CH_2016_NA0017_42_112_20160802_00035.jpg



View of the culvert on the upstream of the channel.

Rating **	M	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Gates			
DWR ID	DWR_NA0017_42_c_2012_113			

Action/Comments

Inspector Comments: Slide gates appeared to be in good operational condition, but gate wheels were missing from the gate.

Photo 1 of 1 : CH_2016_NA0017_42_113_20160802_00036.jpg



View of the slide gate on the upstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Hewit Lane / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_16			
Action/Comments				
Inspector Comments: Walnut tree exists on left side of the shoulder. It doesn't obstructed the flow, but it could fall down in the creek.				

Photo 1 of 2 : CH_2016_NA0017_42_16_20160802_00037.jpg



View of the vegetation on the channel looking downstream during 2016 inspection.

Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_16			

Photo 2 of 2 : CH_2016_NA0017_42_16_20160613_00004.jpg



View of the channel looking downstream during 2015 inspection.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_17			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Hewit Lane / Down (cont)

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_18			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_19			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_20			
Action/Comments				
Inspector Comments: No trash or debris are present in the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Up

Rating **	U*	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_21			

Action/Comments

Inspector Comments: Tree branches and vegetation growth on the channel may cause an obstruction in the flow.

Photo 1 of 2 : CH_2016_NA0017_42_21_20160802_00038.jpg



View of the tree branches on the channel looking upstream during 2016 inspection.

Rating **	U*	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_21			

Photo 2 of 2 : CH_2016_NA0017_42_21_20160613_00005.jpg



View of the vegetation looking upstream of the channel.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_22			

Action/Comments

Inspector Comments: No sedimentation was found during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Up (cont)

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_23			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_24			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_25			

Action/Comments

Inspector Comments: No debris were present during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Down

Rating **	U*	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_26			
Action/Comments				
Inspector Comments: Various lengths of logs, and vegetation growth appeared to impede the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_42_26_20160802_00039.jpg



View of heavy vegetation looking downstream of the channel during 2016 inspection.

Rating **	U*	Issue No.	26 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_26			

Photo 2 of 2 : CH_2016_NA0017_42_26_20160613_00006.jpg



View of heavy vegetation looking downstream of the channel.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_28			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_29			

Action/Comments

Inspector Comments: Existing revetments were found.

Photo 1 of 1 : CH_2016_NA0017_42_29_20160802_00040.jpg



View of existing revetments on the right bank of the channel looking downstream.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_30			

Action/Comments

Inspector Comments: A broken pipe was found on the bank of the channel during inspection.

Photo 1 of 1 : CH_2016_NA0017_42_30_20160613_00007.jpg



View of the broken pipe on the downstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up

Rating **	M	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_31			

Action/Comments

Inspector Comments: Vegetation exists on the channel, and woody vegetation may obstruct the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_42_31_20160802_00041.jpg



View of the channel looking upstream during 2016 inspection.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_32			

Action/Comments

Inspector Comments: No shoaling or sedimentation present on the channel.

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_33			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_34			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_35			

Action/Comments

Inspector Comments: Minimal trash was present on the channel during inspection.

Photo 1 of 1 : CH_2016_NA0017_42_35_20160802_00042.jpg



View of debris on the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_36			
Action/Comments				
Inspector Comments: Minimal vegetation on the channel should not obstruct the flow.				

Photo 1 of 1 : CH_2016_NA0017_42_36_20160802_00043.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_37			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_38			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_39			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

Mariposa Rd / Up

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_41			

Action/Comments

Inspector Comments: Minimal vegetation on the channel should not impede the flow.

Photo 1 of 2 : CH_2016_NA0017_42_41_20160802_00044.jpg



View of upstream of the channel during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	41 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_41			

Action/Comments

Inspector Comments: Minimal vegetation on the channel should not impede the flow.

Photo 2 of 2 : CH_2016_NA0017_42_41_20160613_00011.jpg



View of upstream of the channel during 2015 inspection.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_42			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_43			

Action/Comments

Inspector Comments: No erosion observed at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_44			

Action/Comments

Inspector Comments: Existing revetments appear to be properly maintained.

No Photos

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_45			

Action/Comments

Inspector Comments: No trash or other obstructions are present in the channel.

No Photos

Check Point / View

Mariposa Rd / Down

Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_46			

Action/Comments

Inspector Comments: Vegetation growth may obstruct the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_42_46_20160802_00045.jpg



View of vegetation on the downstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Down (cont)

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_47			
Action/Comments				
Inspector Comments: No sedimentaion is present.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_48			
Action/Comments				
Inspector Comments: No erosion observed at this location.				

No Photos

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_49			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Down (cont)

Rating **	M	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_50			

Action/Comments

Inspector Comments: Trash and debris were present in the channel and under the bridge during the inspection, but it may not impede the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_42_50_20160802_00046.jpg



View of debris in the downstream end of the channel.

Check Point / View

Highway 99 / Up

Rating **	M	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_51			

Action/Comments

Inspector Comments: Minimal vegetation on the channel may impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_51_20160803_00047.jpg



View of the vegetation on the channel looking upstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up (cont)

Rating **	M	Issue No.	51 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_51			
Action/Comments				
Inspector Comments: Minimal vegetation on the channel may impede the flow of the channel.				

Photo 2 of 2 : CH_2016_NA0017_42_51_20160613_00015.jpg



View of the vegetation on the channel looking upstream during 2015 inspection.

Rating **	M	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_52			
Action/Comments				
Inspector Comments: Sedimentation is present at this location.				

Photo 1 of 1 : CH_2016_NA0017_42_52_20160613_00017.jpg



View of sedimentation on the upstream of the channel.

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_53			
Action/Comments				
Inspector Comments: No erosion was present during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up (cont)

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_54			
Action/Comments				
Inspector Comments: No revetments was found at this location.				

No Photos

Rating **	M	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_55			
Action/Comments				
Inspector Comments: Trash, and various debris may obstruct the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_42_55_20160803_00048.jpg



View of debris on the upstream of the channel during 2016 inspection.

Rating **	M	Issue No.	55 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_55			

Photo 2 of 2 : CH_2016_NA0017_42_55_20160613_00018.jpg



View of the encroachments on the upstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_56			

Action/Comments

Inspector Comments: Minimal vegetation does not impede the flow on the channel.

Photo 1 of 2 : CH_2016_NA0017_42_56_20160803_00049.jpg



View of the channel looking downstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_42_56_20160613_00019.jpg



View of the downstream end of the channel.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_57			

Action/Comments

Inspector Comments: No sedimentation is present during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_58			

Action/Comments

Inspector Comments: No erosion is present.

No Photos

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_59			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_60			

Action/Comments

Inspector Comments: Some trash was present during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Pock Lane / Up

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_61			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_61_20160803_00050.jpg



View of the channel looking upstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_42_61_20160613_00020.jpg



View of the channel looking upstream during 2015 inspection.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_62			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Pock Lane / Up (cont)

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_63			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_64			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_65			

Action/Comments

Inspector Comments: No trash or debris is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Pock Lane / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_66			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_66_20160803_00051.jpg



View of the vegetation looking downstream of the channel during 2016 inspection.

Rating **	A	Issue No.	66 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_66			

Photo 2 of 2 : CH_2016_NA0017_42_66_20160613_00022.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_67			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Pock Lane / Down (cont)

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_68			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_69			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_70			
Action/Comments				
Inspector Comments: No trash or debris is present in the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

South B Street / Up

Rating **	A	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_71			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel.

Photo 1 of 2 : CH_2016_NA0017_42_71_20160803_00052.jpg



View of vegetation on the channel looking upstream during 2016 inspection.

Rating **	A	Issue No.	71 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_71			

Photo 2 of 2 : CH_2016_NA0017_42_71_20160613_00023.jpg



View of vegetation on the channel looking upstream.

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_72			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

South B Street / Up (cont)

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_73			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_74			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_75			

Action/Comments

Inspector Comments: Moderate trash was present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

South B Street / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation on the channel may not impede the flow.

Photo 1 of 2 : CH_2016_NA0017_42_76_20160803_00053.jpg



View of the vegetation looking downstream during 2016 inspection.

Rating **	A	Issue No.	76 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_76			

Photo 2 of 2 : CH_2016_NA0017_42_76_20160613_00024.jpg



View of the channel looking downstream on 2015 inspection.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_77			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

South B Street / Down (cont)

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_78			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_79			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_80			

Action/Comments

Inspector Comments: No trash or debris was present during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Airport Way / Up

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_81			
Action/Comments				
Inspector Comments: Moderate vegetation present in channel may impede the flow.				

Photo 1 of 1 : CH_2016_NA0017_42_81_20160803_00054.jpg



View of the vegetation on the channel looking upstream.

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_82			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_83			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Airport Way / Up (cont)

Rating **	N	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_84			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_85			

Action/Comments

Inspector Comments: No trash or debris was present in the channel.

No Photos

Check Point / View

Airport Way / Down

Rating **	M	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_86			

Action/Comments

Inspector Comments: Moderate woody vegetation may impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_86_20160803_00055.jpg



View of the vegetation on the channel looking downstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District


Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Airport Way / Down (cont)

Rating **	M	Issue No.	86 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_86			
Action/Comments				
Inspector Comments: Moderate woody vegetation may impede the flow of the channel.				

Photo 2 of 2 : CH_2016_NA0017_42_86_20160613_00027.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_87			
Action/Comments				
Inspector Comments: No shoaling was found during the inspection.				

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_88			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Airport Way / Down (cont)

Rating **	N	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_89			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_90			

Action/Comments

Inspector Comments: No trash or debris was present during the inspection.

No Photos

Check Point / View

Producers Drive / Up

Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_91			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_42_91_20160803_00056.jpg



View of the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Producers Drive / Up (cont)

Rating **	A	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_92			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_93			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_94			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Producers Drive / Up (cont)

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_95			

Action/Comments

Inspector Comments: No trash was found during the inspection.

No Photos

Check Point / View

Producers Drive / Down

Rating **	A	Issue No.	96	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_96			

Action/Comments

Inspector Comments: Minimal vegetation was found, but the flow is not impeded.

Photo 1 of 2 : CH_2016_NA0017_42_96_20160803_00057.jpg



View of the channel looking downstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_42_96_20160613_00029.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	96 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_96			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Producers Drive / Down (cont)

Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_97			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_98			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_99			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View				
Producers Drive / Down (cont)				
Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_100			
Action/Comments				
Inspector Comments: No trash or debris is present in the channel.				

No Photos

Check Point / View				
McKinley Avenue / Up				
Rating **	M	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_101			
Action/Comments				
Inspector Comments: Vegetation, logs and other debris may impede the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_42_101_20160803_00058.jpg



View of the heavy vegetation on the channel looking upstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

McKinley Avenue / Up (cont)

Rating **	M	Issue No.	101 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_101			

Action/Comments

Inspector Comments: Vegetation, logs and other debris may impede the flow of the channel.

Photo 2 of 2 : CH_2016_NA0017_42_101_20160613_00030.jpg



View of the heavy vegetation on the channel looking upstream.

Rating **	M	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_102			

Action/Comments

Inspector Comments: Non aquatic grasses and sedimentation were present during the inspection.

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_103			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

McKinley Avenue / Up (cont)

Rating **	N	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_104			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_105			

Action/Comments

Inspector Comments: Trash and debris are present in the channel.

Photo 1 of 1 : CH_2016_NA0017_42_105_20160803_00059.jpg



View of debris on the upstream end of the channel during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

McKinley Avenue / Down

Rating **	M	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_106			

Action/Comments

Inspector Comments: Vegetation and debris may impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_42_106_20160803_00060.jpg



View of the channel looking downstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_42_106_20160613_00031.jpg



View of the vegetation looking downstream of the channel.

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_107			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

McKinley Avenue / Down (cont)

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_108			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_109			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_110			

Action/Comments

Inspector Comments: No trash or debris are present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
South Littlejohn Creek

Channel Rating	M
Date of Inspection	7/20/2016 - 7/26/2016
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Farmington Dam / Up

Rating **	A	Issue No.	119	GPS Lat/Long
Issue Type +	Ma	Location *		37.900580 °
Category	Rivers, Channels & Designated Flood			-120.936018 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2014_119			
Action/Comments				
Inspector Comments: The gate appears to be functional.				

Photo 1 of 1 : CH_2016_NA0017_44_119_20160726_00051.jpg



View of the release gate from Farmington Dam looking upstream of the creek.

Check Point / View

Farmington Dam / Down

Rating **	M	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.914340 °
Category	Rivers, Channels & Designated Flood			-120.937860 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_6			
Action/Comments				
Inspector Comments: Vegetation in the channel may impede the flow.				

Photo 1 of 1 : CH_2016_NA0017_44_6_20160726_00052.jpg



View of the vegetation on the channel looking downstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View				
Farmington Dam / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present in the channel.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_8			
Action/Comments				
Inspector Comments: Erosion is repaired.				

Photo 1 of 2 : CH_2016_NA0017_44_8_20160726_00053.jpg



Erosion on the left bank of the channel is repaired. The picture was taken looking downstream during 2016 inspection.

Rating **	A	Issue No.	8 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_8			

Photo 2 of 2 : CH_2016_NA0017_44_8_20160720_00002.jpg



View of the erosion on the left of the channel looking downstream during 2015 inspection.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View				
Farmington Dam / Down (cont)				
Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_9			
Action/Comments				
Inspector Comments: Existing riprap appeared to be maintained.				

Photo 1 of 1 : CH_2016_NA0017_44_9_20160726_00054.jpg



View of the existing revetments looking downstream during 2016 inspection.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.914340 °
Category	Rivers, Channels & Designated Flood			-120.937860 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_10			
Action/Comments				
Inspector Comments: No debris is present in the channel.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Wedding Chappel Crossing / Up

Rating **	A	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		37.900307 °
Category	Rivers, Channels & Designated Flood			-120.938492 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2013_99			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_44_99_20160726_00055.jpg



View of the vegetation on the channel looking upstream.

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2013_100			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2013_101			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Wedding Chappel Crossing / Up (cont)

Rating **	N	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2013_112			

Action/Comments

Inspector Comments: No revetments exist at this location.

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_103			

Action/Comments

Inspector Comments: No debris was found during inspection.

No Photos

Rating **	M	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2013_108			

Action/Comments

Inspector Comments: The pipe appeared to be in good condition, but accumulated debris may block the flow inside the pipe.

Photo 1 of 1 : CH_2016_NA0017_44_108_20160726_00056.jpg



View of the pipe looking upstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Wedding Chappel Crossing / Down

Rating **	U	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		37.900332 °
Category	Rivers, Channels & Designated Flood			-120.939298 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2013_104			

Action/Comments

Inspector Comments: Heavy vegetation growth will impede the flow and may block approximately 50% capacity of the channel.

Photo 1 of 2 : CH_2016_NA0017_44_104_20160726_00057.jpg



View of the vegetation on the downstream of the channel during 2016 inspection.

Rating **	U	Issue No.	104 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.900332 °
Category	Rivers, Channels & Designated Flood			-120.939298 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2013_104			

Photo 2 of 2 : CH_2016_NA0017_44_104_20160720_00040.jpg



View of the vegetation on the downstream of the channel during 2015 inspection.

Rating **	A	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2013_105			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Wedding Chappel Crossing / Down (cont)

Rating **	A	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2013_106			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

Rating **	U	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_107			

Action/Comments

Inspector Comments: Various debris and tree trunks were present in the channel during the inspection.

Photo 1 of 1 : CH_2016_NA0017_44_107_20160720_00042.jpg



View of obstructions on the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Henry Road / Up

Rating **	A	Issue No.	141	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_141			

Action/Comments

Inspector Comments: Minimal vegetation was present, but the flow is not impeded.

Photo 1 of 1 : CH_2016_NA0017_44_141_20160726_00058.jpg



View of vegetation on the upstream of the channel.

Rating **	A	Issue No.	142	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2015_142			

Action/Comments

Inspector Comments: No sedimentation was present.

No Photos

Rating **	A	Issue No.	143	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2015_143			

Action/Comments

Inspector Comments: No erosion was found.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Henry Road / Up (cont)

Rating **	M	Issue No.	144	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2015_144			

Action/Comments

Inspector Comments: Debris was found that could obstruct the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_44_144_20160726_00060.jpg




View of debris on the channel looking upstream.

Rating **	A	Issue No.	150	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2015_150			

Action/Comments

Inspector Comments: The pipe appears to be free of debris and does not appear to impede the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_44_150_20160726_00059.jpg



View of the pipe looking upstream from the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Henry Road / Down

Rating **	M	Issue No.	146	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_146			
Action/Comments				
Inspector Comments: Vegetation growth may impede the flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_44_146_20160726_00061.jpg



View of the vegetation on the downstream of the channel.

Rating **	A	Issue No.	147	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2015_147			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was present.				

No Photos

Rating **	A	Issue No.	148	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2015_148			
Action/Comments				
Inspector Comments: No erosion was present during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Henry Road / Down (cont)

Rating **	A	Issue No.	149	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2015_149			

Action/Comments

Inspector Comments: No trash was present.

No Photos

Check Point / View

Escalon Bellota Rd / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_21			

Action/Comments

Inspector Comments: No vegetation was impeding the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_44_21_20160802_00062.jpg



View of the channel looking upstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_44_21_20160720_00007.jpg



View of the channel looking upstream during 2015 inspection.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_21			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Escalon Bellota Rd / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_22			
Action/Comments				
Inspector Comments: No sedimentation is present in the channel.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_23			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_24			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 1 of 1 : CH_2016_NA0017_44_24_20160802_00063.jpg



Existing revetments are properly maintained looking upstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Escalon Bellota Rd / Up (cont)

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_25			
Action/Comments				
Inspector Comments: No trash or debris is present in the channel.				

No Photos

Check Point / View

Escalon Bellota Rd / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_26			
Action/Comments				
Inspector Comments: Minimal vegetation was found in the channel.				

Photo 1 of 2 : CH_2016_NA0017_44_26_20160802_00064.jpg



View of the channel looking downstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_44_26_20160720_00011.jpg



View of the channel looking downstream during 2015 inspection.

Rating **	A	Issue No.	26 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_26			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Escalon Bellota Rd / Down (cont)

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present in this channel.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_28			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_29			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 1 of 2 : CH_2016_NA0017_44_29_20160802_00065.jpg



View of the revetments on the left of the channel looking downstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Escalon Bellota Rd / Down (cont)

Rating **	A	Issue No.	29 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_29			

Action/Comments

Inspector Comments: Existing riprap is properly maintained.

Photo 2 of 2 : CH_2016_NA0017_44_29_20160720_00013.jpg



View of the revetments on the left of the channel looking downstream.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_30			

Action/Comments

Inspector Comments: No trash or debris are present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Stanley Rd / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation will not impede the flow of the channel.

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_31			

Photo 1 of 2 : CH_2016_NA0017_44_31_20160802_00066.jpg



View of the channel looking upstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_44_31_20160720_00015.jpg



View of the channel looking upstream during 2015 inspection.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_32			

Action/Comments

Inspector Comments: No sediment was present in this channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Stanley Rd / Up (cont)

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_33			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_34			

Action/Comments

Inspector Comments: Existing revetments were maintained properly on the channel bank.

Photo 1 of 1 : CH_2016_NA0017_44_34_20160802_00067.jpg



View of the existing revetments on the right channel bank looking upstream.

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_35			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District


Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Stanley Rd / Down

Rating **	M	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_36			
Action/Comments				
Inspector Comments: Tree branches might obstruct the downstream flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_44_36_20160802_00068.jpg



Tree branches might obstruct the flow of the channel looking downstream.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_37			
Action/Comments				
Inspector Comments: No sediment was present in this channel.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_38			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Stanley Rd / Down (cont)

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_39			

Action/Comments

Inspector Comments: No revetments are found at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

Van Allen Rd / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_41			

Action/Comments

Inspector Comments: Significant amounts of cat tails were present in the channel.

Photo 1 of 1 : CH_2016_NA0017_44_41_20160802_00069.jpg



View of the vegetation on the channel looking upstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Up (cont)

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_42			
Action/Comments				
Inspector Comments: No sediment was present in this channel.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_43			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_44			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained.				

Photo 1 of 1 : CH_2016_NA0017_44_44_20160802_00070.jpg



View of existing revetments on the channel bank looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Up (cont)

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_45			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

Check Point / View

Van Allen Rd / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_46			

Action/Comments

Inspector Comments: The vegetation growth around the channel is not impeding the flow.

Photo 1 of 2 : CH_2016_NA0017_44_46_20160802_00071.jpg



View of the vegetation on the channel looking downstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Down (cont)

Rating **	A	Issue No.	46 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_46			

Action/Comments

Inspector Comments: The vegetation growth around the channel is not impeding the flow.

Photo 2 of 2 : CH_2016_NA0017_44_46_20160720_00021.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_47			

Action/Comments

Inspector Comments: No sediment was present during inspection.

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_48			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Van Allen Rd / Down (cont)

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_49			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH_2016_NA0017_44_49_20160802_00072.jpg



View of the existing revetments looking downstream.

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	En	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_50			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_51			
Action/Comments				
Inspector Comments: Minimal vegetation is present in the channel.				

Photo 1 of 1 : CH_2016_NA0017_44_51_20160802_00073.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_52			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_53			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	151	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2016_151			

Action/Comments

Inspector Comments: Existing revetments are properly maintained.

Photo 1 of 1 : CH_2016_NA0017_44_151_20160802_00074.jpg



View of the existing revetments on the upstream of the channel.

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_55			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_56			

Action/Comments

Inspector Comments: Vegetation and some waddy vegetation was present on the channel, but it may not impede the flow of the channel.

Photo 1 of 2 : CH_2016_NA0017_44_56_20160802_00075.jpg



View of the vegetation on the channel looking downstream during 2016 inspection.

Rating **	A	Issue No.	56 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_56			

Photo 2 of 2 : CH_2016_NA0017_44_56_20160720_00024.jpg



View of the vegetation on the channel looking downstream.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_57			

Action/Comments

Inspector Comments: No sedimentation is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Mariposa Rd / Down (cont)

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_58			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

Rating **	A	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_59			

Action/Comments

Inspector Comments: Existing revetments appears to be undamaged.

Photo 1 of 1 : CH_2016_NA0017_44_59_20160720_00025.jpg



View of existing revetments on the channel banks looking downstream.

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	En	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_60			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_61			

Action/Comments

Inspector Comments: Minimal vegetation was present in the channel.

Photo 1 of 2 : CH_2016_NA0017_44_61_20160802_00076.jpg



View of the channel looking upstream during 2016 inspection.

Photo 2 of 2 : CH_2016_NA0017_44_61_20160720_00026.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_62			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_63			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_64			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH_2016_NA0017_44_64_20160802_00077.jpg



View of existing riprap on the upstream of the channel.

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_65			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	M	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_70			

Action/Comments

Inspector Comments: A broken pipe with a missing flapgate was found on the upstream side of the channel.

Photo 2 of 1 : CH_2016_NA0017_44_70_20160720_00030.jpg



View of a pipe with missing flap gate on the upstream of the channel.

Check Point / View

Jack Tone Rd / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_66			

Action/Comments

Inspector Comments: Minimal vegetation was present on the channel.

Photo 1 of 2 : CH_2016_NA0017_44_66_20160802_00078.jpg



View of the channel looking downstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	66 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_66			
Action/Comments				
Inspector Comments: Minimal vegetation was present on the channel.				

Photo 2 of 2 : CH_2016_NA0017_44_66_20160720_00028.jpg



View of the vegetation in the channel looking downstream.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_67			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_68			
Action/Comments				
Inspector Comments: No erosion is present on the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_69			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

Photo 1 of 1 : CH_2016_NA0017_44_69_20160802_00079.jpg



View of the existing riprap on the channel bank looking downstream.

Check Point / View

Austin Rd / Up

Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_71			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel, but the flow is not impeded.

Photo 1 of 1 : CH_2016_NA0017_44_71_20160803_00080.jpg



View of vegetation on the upstream side of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Up (cont)

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_72			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_73			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_74			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View				
Austin Rd / Up (cont)				
Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	En	Location *		37.872482°
Category	Rivers, Channels & Designated Flood			-121.182910°
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_75			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

Check Point / View				
Austin Rd / Down				
Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_76			
Action/Comments				
Inspector Comments: Minimal vegetation growth is found, but it doesn't appear to impede the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_44_76_20160803_00081.jpg



View of the vegetation on the downstream of the channel during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Down (cont)

Rating **	A	Issue No.	76 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation growth is found, but it doesn't appear to impede the flow of the channel.

Photo 2 of 2 : CH_2016_NA0017_44_76_20160720_00032.jpg



View of the vegetation on the downstream end of the channel.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_77			

Action/Comments

Inspector Comments: No sediment was present during inspection.

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_78			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Down (cont)

Rating **	A	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_79			

Action/Comments

Inspector Comments: Existing revetments are properly maintained.

Photo 1 of 1 : CH_2016_NA0017_44_79_20160803_00082.jpg



View of the revetments on the downstream of the channel.

Rating **	M	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_80			

Action/Comments

Inspector Comments: Debris was found, but it may not impede the flow of the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_81			
Action/Comments				
Inspector Comments: Vegetation growth may impede the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_44_81_20160803_00085.jpg



View of the vegetation looking upstream of the channel during 2016 inspection.

Rating **	M	Issue No.	81 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_81			

Photo 2 of 2 : CH_2016_NA0017_44_81_20160720_00034.jpg



View of vegetation on the upstream end of the channel.

Rating **	M	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_82			
Action/Comments				
Inspector Comments: Non aquatic grasses are present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up (cont)

Rating **	M	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_83			
Action/Comments				
Inspector Comments: Erosion is present on the bank of the channel.				

Photo 1 of 2 : CH_2016_NA0017_44_83_20160803_00086.jpg



Updated picture of the erosion on the left bank of the channel looking upstream.

Rating **	M	Issue No.	83 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_83			

Photo 2 of 2 : CH_2016_NA0017_44_83_20160720_00035.jpg



View of the erosion on the channel bank looking upstream.

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_84			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained at this location.				

Photo 1 of 1 : CH_2016_NA0017_44_84_20160803_00087.jpg



View of the existing revetments on the upstream end of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_85			
Action/Comments				
Inspector Comments: No trash was present during the inspection.				

No Photos

Check Point / View

Highway 99 / Down

Rating **	M	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_86			
Action/Comments				
Inspector Comments: Vegetation may impede the flow of the channel.				

Photo 1 of 2 : CH_2016_NA0017_44_86_20160803_00083.jpg



View of the vegetation looking downstream of the channel during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Down (cont)

Rating **	M	Issue No.	86 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_86			
Action/Comments				
Inspector Comments: Vegetation may impede the flow of the channel.				

Photo 2 of 2 : CH_2016_NA0017_44_86_20160720_00037.jpg



View of the vegetation looking downstream of the channel.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_87			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_88			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_89			
Action/Comments				
Inspector Comments: Existing riprap was properly maintained at this location.				

Photo 1 of 1 : CH_2016_NA0017_44_89_20160803_00084.jpg



View of the existing revetments on the downstream of the channel.

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_90			
Action/Comments				
Inspector Comments: No trash was present at this location.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

El Dorado Rd. / Up

Rating **	A	Issue No.	120	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_120			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel. Tree branches may fall in the channel in future.

Photo 1 of 1 : CH_2016_NA0017_44_120_20160803_00088.jpg



View of the channel looking upstream.

Rating **	A	Issue No.	121	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2014_121			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	122	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2014_122			

Action/Comments

Inspector Comments: No erosion is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

El Dorado Rd. / Up (cont)

Rating **	N	Issue No.	123	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_123			

Action/Comments

Inspector Comments: There is no revetment at this location.

No Photos

Rating **	A	Issue No.	124	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_124			

Action/Comments

Inspector Comments: No trash or debris was found on the channel.

No Photos

Check Point / View

El Dorado Rd. / Down

Rating **	A	Issue No.	125	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_125			

Action/Comments

Inspector Comments: Tree branches may fall into the channel, but the flow is not impeded.

Photo 1 of 1 : CH_2016_NA0017_44_125_20160803_00089.jpg



View of the vegetation on the downstream of the channel during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

El Dorado Rd. / Down (cont)

Rating **	A	Issue No.	126	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2014_126			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	127	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2014_127			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

Rating **	N	Issue No.	128	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_128			
Action/Comments				
Inspector Comments: There is no revetment at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	07/20/2016 07/26/2016	Pavel Kazi

Check Point / View

El Dorado Rd. / Down (cont)

Rating **	A	Issue No.	129	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_129			

Action/Comments

Inspector Comments: No trash or debris was found on the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
South Littlejohn Creek North Branch

Channel Rating	A
Date of Inspection	7/21/2016 - 7/26/2016
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Diversion / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_6			
Action/Comments				
Inspector Comments: Minimal vegetation was present in the channel but it is unlikely to impede the flow.				

Photo 1 of 1 : CH_2016_NA0017_45_6_20160802_00016.jpg



View of the confluence looking downstream.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_7			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_8			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Diversion / Down (cont)

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_9			

Action/Comments

Inspector Comments: No revetments exist at this location.

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_10			

Action/Comments

Inspector Comments: No trash was found during inspection.

No Photos

Check Point / View

Jack Tone Rd / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_11			

Action/Comments

Inspector Comments: Minimal vegetation growth was found in the channel, but it is unlikely to impede the flow in the channel.

Photo 1 of 2 : CH_2016_NA0017_45_11_20160802_00017.jpg



View of the channel looking upstream during 2016 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_11			

Action/Comments

Inspector Comments: Minimal vegetation growth was found in the channel, but it is unlikely to impede the flow in the channel.

Photo 2 of 2 : CH_2016_NA0017_45_11_20160613_00002.jpg



View of the vegetation upstream end of the channel.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_12			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_13			

Action/Comments

Inspector Comments: No erosion or bank caving is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_14			

Action/Comments

Inspector Comments: Existing riprap is properly maintained at this location.

Photo 1 of 1 : CH_2016_NA0017_45_14_20160802_00018.jpg



View of the existing riprap on the channel bank looking upstream.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_15			

Action/Comments

Inspector Comments: No trash was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down

Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_16			
Action/Comments				
Inspector Comments: Vegetation growth may obstruct the flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_45_16_20160802_00019.jpg



View of the vegetation on the channel looking downstream.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_17			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

Rating **	M	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_18			
Action/Comments				
Inspector Comments: Minor erosion or bank caving is present.				

Photo 1 of 1 : CH_2016_NA0017_45_18_20160613_00005.jpg



View of bank erosion on the downstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_19			
Action/Comments				
Inspector Comments: Existing revetments appeared to be properly maintained.				

Photo 1 of 1 : CH_2016_NA0017_45_19_20160802_00020.jpg



View of the existing revetments on the channel bank looking downstream.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_20			
Action/Comments				
Inspector Comments: No trash or debris are present at this location.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_21			
Action/Comments				

Photo 1 of 2 : CH_2016_NA0017_45_21_20160802_00021.jpg



View of the vegetation on the channel looking upstream during 2016 inspection.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_21			
Action/Comments				

Photo 2 of 2 : CH_2016_NA0017_45_21_20160613_00007.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_22			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Up (cont)

Rating **	M	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_23			
Action/Comments				
Inspector Comments: Signs of erosion undercutting bank were found on the right bank of the channel.				

Photo 1 of 1 : CH_2016_NA0017_45_23_20160803_00022.jpg



View of erosion on the right bank of the channel looking upstream.

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_24			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_25			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Austin Rd / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_26			
Action/Comments				
Inspector Comments: Minimal vegetation was found during the inspection, but the flow is unlikely to be impeded.				

Photo 1 of 1 : CH_2016_NA0017_45_26_20160803_00023.jpg



View of downstream of the channel.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_28			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View			
Austin Rd / Down (cont)			
Rating **	N	Issue No.	29
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0017_45_c_2012_29		
Action/Comments			
Inspector Comments: No revetment exists at this location.			

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	En	Location *		
Category	Rivers, Channels & Designated Flood			
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_30			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

Check Point / View			
Confluence at Airport Way / Up			
Rating **	A	Issue No.	31
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0017_45_c_2012_31		
Action/Comments			
Inspector Comments: Minimal scattered vegetation is unlikely to impede the flow of the channel.			

Photo 1 of 1 : CH_2016_NA0017_45_31_20160803_00024.jpg



View of the confluence looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Confluence at Airport Way / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_32			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_33			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_34			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Confluence at Airport Way / Up (cont)

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_35			

Action/Comments

Inspector Comments: No trash or debris is present.

No Photos

Check Point / View

Confluence at Airport Way / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_36			

Action/Comments

Inspector Comments: Minimal scattered vegetation is unlikely to impede the flow of the channel.

Photo 1 of 1 : CH_2016_NA0017_45_36_20160803_00025.jpg



View of the downstream of the channel during 2016 inspection.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_37			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Confluence at Airport Way / Down (cont)

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_38			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_39			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_40			
Action/Comments				
Inspector Comments: No trash or debris is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2013_41			
Action/Comments				
Inspector Comments: Dense vegetation may impede the flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_45_41_20160803_00028.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127°
Category	Rivers, Channels & Designated Flood			-121.219201°
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2013_42			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127°
Category	Rivers, Channels & Designated Flood			-121.219201°
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2013_43			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained.				

Photo 1 of 1 : CH_2016_NA0017_45_43_20160803_00029.jpg



View of the existing revetment looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2013_44			
Action/Comments				
Inspector Comments: No trash was found at this location.				

No Photos

Check Point / View

Highway 99 / Down

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2013_45			
Action/Comments				
Inspector Comments: Vegetation was not imepeding the flow of the channel.				

Photo 1 of 1 : CH_2016_NA0017_45_45_20160803_00026.jpg



View of the channel looking downstream.

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2013_46			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	07/21/2016 07/26/2016	Pavel Kazi

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2013_47			
Action/Comments				
Inspector Comments: No erosion was present during the inspection.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2013_48			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained.				

Photo 1 of 1 : CH_2016_NA0017_45_48_20160803_00027.jpg



View of the revetments on the downstream of the channel.

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c _ 2013_49			
Action/Comments				
Inspector Comments: No trash was present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement